

## RX-8303 (Series Directions For Use)

### 一、 Important notice for correct installations

This hair dryer , as well as the socket , must be placed out of reach of a person using the bath or shower . If directly Connected with the main supply , it should be installed by a qualified technician , to avoid any hazard.

### 二、 Installation instructions

- 1、 Make sure that the rating of your wiring system is adequate for the appliance( $S(\Delta) \geq 0.75\text{mm}^2$ ).
- 2、 Hold the unit in place at the required position for fixing , to the wall marking one holes of 6mm diameter . In order to ensure the best use of your hair dryer we recommend that the upper hole be drilled at a height of 1800mm above floor level . Driving a screw after stuff a screw washer into the drilled hole , keeping a distance of about 2.5mm between bottom of screw and surface of wall . Marking a hole of  $\Phi 6\text{mm}$  under meath for holding . (All above accessories are supplied).
- 3、 If it is preferable to connect the hair dryer directly to the electric network , remove the plug on power cord of the hair Dryer , then connect to the power supply . (Must be connected to the power supply accordance with electric install manual).
- 4、 Hang hair dryer on upper screw with setting hole at back , tighten the screw .

**Warning : this operation must be carried out by a qualified electrician .**

### 三、 Directions for use :

To start the hair dryers , remove the handgrip form it position . Air blow and temperature can be adjusted by selecting one of The three positions :

- Maximum power
- Medium power
- Minimum power

Shaver models are fitted 115-230V shaver sockets . Never connect other appliances like coffee machines or heaters : the shaver Socket has to be utilized only for shavers . For cleaning plastic , we recommend to use a damp cloth . Never use abrasive cleaners For not damaging the finish .

The supplier is not responsible for damager the people or things in case the product has not been installed

### 四、 Pecification

Model	RX-8303-1	RX-8303-2	Note
Meas.	250×185×100	250×185×100	
Power supply	220V/50Hz	220V/50Hz	Optional
Max . power	1000W	1000W	
Temperature of	60°C ± 5°C	60°C ± 5°C	
Max . speed	13-14m/s	13-14m/s	6cm of hose outlet
Shaver socket	NO	YES	